

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11

100




FIG. 12




FIG. 13




FIG. 14

100




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21





FIG. 22



(a)

(b)

FIG. 23




FIG. 24




Figure 1 is a schematic diagram of a mechanical assembly in a perspective view. The assembly includes a base plate 101. A vertical section line A-A is indicated. A component 40 is mounted on the base plate. A bracket 60 is attached to component 40, and a pin 62 is inserted through the bracket. A component 70 is also attached to component 40. Arrows 11, 12, and 13 indicate directions of movement or force. A dashed line 14 is also shown.






FIG. 27




FIG. 28




FIG. 29




FIG. 30





FIG. 31



(a)

(b)

FIG. 32




FIG. 33






FIG. 34




(a)

(b)

FIG. 35



(a)



(b)

FIG. 36




FIG. 37




FIG. 38





FIG. 39



200




FIG. 41




FIG. 42




FIG. 43




FIG. 44




FIG. 45  
PRIOR ART 300




FIG. 46  
PRIOR ART





FIG. 47  
PRIOR ART



۲۷

